O JUL 28 MIG LES

Application No.: 10/051,980
Amdt. Date: July 24, 2003
Reply to Office Action of March 24, 2003
Attorney Docket No: 42390P9482D
Replacement Sheet
Sheet: 2 of 2

Start Place an incomplete chip package in bottom half of mold 310 Mate top mold half with bottom mold half 315 Inject mixed epoxy into cavity 320 Remove mold halves 325 Remove runner 330 **End**

Figure 3